# ALLOWANCE PARTS LIST (APL)

| EQUIPMENT/COMPONENT NOMENCLATURE/CHARACTERISTICS | TECHNICAL DOCUMENT NUMBER | MANUAL | IDENTIFICATION NO. | DATE | PAGE |
|---|---|---|---|---|---|
| TOASTER,POP-UP,ELECTR | | PLAN | 43A100008 | 08/2010 | 1 |

CHARACTERISTICS

MFR-STAR MFG INTL SAINT LOUIS MO
NAVCOM PLAN-
MFR DWG-
MFR ID-T4-120V
PATTERN NO-
EQUIP SPEC-
NSN-NONE
LAPL-NSWC-SSES ENG REVIEW
TYPE-TOASTER,POP-UP
NO OF SLOTS-4
VOLTAGE-120AC
HEIGHT-9-3/16IN
WIDTH-11-7/16IN
DEPTH-13-3/8IN
SLICES PER HOUR-250
AMPS-18.3
APPROX. SHIP WEIGHT-21LBS
APL ORIGIN-NEW CONSTRUCTION LPD17 CLASS
PCCN-N6ASPP
TSA-NSWCCD-SSES PAUL LAFOUNTAIN CODE 945
PA-NAVICP-M
NOTE:EQUIPMENT APPROVED FOR SHIPBOARD USE, BUT IS
CONSIDERED A CONSUMABLE ITEM PER NSWCCD-SSES CODE 974.
NO LOGISTICS SUPPORT TO BE PROVIDED.
LSSC-FD
CAGE-60105
CCF DATE -03 10

| PARTMEC | SOURCE | MAINT | RECOV | NOTES | QTY. IN ONE EQPT./ COMP. | UI | ALL ITEM | ON BOARD ALLOWANCE TABLE — NUMBER OF EQUIPMENT/COMPONENTS 1 | 2 | 3 | 4 | 5-8 | 9-20 | 21-50 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | | | | |

| REFERENCE SYMBOL NUMBER | ITEM NAME | STOCK NUMBER | PARTMEC | SOURCE | MAINT | RECOV | NOTES | QTY. IN ONE EQPT./ COMP. | UI | AI | 1 | 2 | 3 | 4 | 5-8 | 9-20 | 21-50 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| | | | | | | | | | | | | | | | | | |

| SHIP TYPE & HULL NO. | PAGE | ALLOWANCE PARTS LIST (APL) PROVISIONING | IDENTIFICATION NO. | DATE | PAGE |
|---|---|---|---|---|---|
| | | | 43A100008 | 08/2010 | 1 |



Printed by IHS, Inc.
15 Inverness Way East, Englewood, CO 80112

# ALLOWANCE PARTS LIST (APL)

| EQUIPMENT/COMPONENT NOMENCLATURE/CHARACTERISTICS | TECHNICAL DOCUMENT NUMBER | MANUAL | IDENTIFICATION NO. | DATE | PAGE |
|---|---|---|---|---|---|
| TOASTER,POP-UP,ELECTR | | PLAN | 43A100008 | 08/2010 | 2 |

CHARACTERISTICS

THE LSSC OF FD INDICATES THE FOLLOWING:

1ST CHARACTER POSITION- F NO SUPPORT: SUPPLY SUPPORT IS NOT PROVIDED FOR THIS EQUIPMENT FOR THE REASON INDICATED BY THE SECOND POSITION OF THE LOGISTICS SUPPORT STATUS CODE.

2ND CHARACTER POSITION- D LOCAL SUPPORT METHOD: THERE IS NO ALLOWANCE OF ON BOARD SPARES/REPAIR PARTS FOR THIS EQUIPMENT IN THE STOCK NUMBER SEQUENCE LIST. SOME REPAIR PARTS MAY BE ON BOARD DUE TO IDENTICAL PARTS IN OTHER EQUIPMENTS INSTALLED ON BOARD. SUPPORT THIS EQUIPMENT WITH PARTS ALREADY IN THE SUPPLY SYSTEM OR FROM SPECIAL REPAIR FACILITIES OR BY LOCAL PROCUREMENT WHEN REQUIRED AND IF EQUIPMENT IS NOT EXPENDABLE.

E N D

| PARTMEC | SOURCE | MAINT | RECOV | NOTES | QTY. IN ONE EQPT./ COMP. | UI | ALL ITEM | ON BOARD ALLOWANCE TABLE — NUMBER OF EQUIPMENT/COMPONENTS 1 | 2 | 3 | 4 | 5-8 | 9-20 | 21-50 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|

| REFERENCE SYMBOL NUMBER | ITEM NAME | STOCK NUMBER | PARTMEC | SOURCE | MAINT | RECOV | NOTES | QTY. IN ONE EQPT./ COMP. | UI | AI | 1 | 2 | 3 | 4 | 5-8 | 9-20 | 21-50 |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|

| SHIP TYPE & HULL NO. | PAGE | ALLOWANCE PARTS LIST (APL) PROVISIONING | IDENTIFICATION NO. | DATE | PAGE |
|---|---|---|---|---|---|
| | | | 43A100008 | 08/2010 | 2 |



Printed by IHS, Inc.
15 Inverness Way East, Englewood, CO 80112